

THREAD THROUGH KNOT

* Attach Insulator For Positive Charged Wire



3 CRIMPING SLEEVES

* Attach Insulator For Positive Charged Wire



SQUARE KNOT



FIGURE EIGHT KNOT



WESTERN UNION SPLICE

Designed _____ Date	NRCS Natural Resources Conservation Service United States Department Of Agriculture	JOINING METHODS HI–TENSILE WIRE	IL–ENG–800 Drawing No.
Drawn M.Quinones 4/14			Page 1 of 1
Checked _____			Sheet of
Approved _____			