

Appendix C

Supporting Figures and Photographs



Photograph C-1. Flooding in Dammeron Valley, Utah.



Photograph C-2. Flooding in Dammeron Valley, Utah.



Photograph C-3. Flooding in Dammeron Valley, Utah.



Photograph C-4. Flooding in Dammeron Valley, Utah.



Photograph C-5. Flooding in Dammeron Valley, Utah.



Photograph C-6. Damaged historic irrigation ditch near Santa Clara River.



Photograph C-7. Second damaged historic irrigation ditch near Santa Clara River.



Photograph C-8. Erosion along the Santa Clara River at the Shivwits site.



Photograph C-9. Gully erosion at the Shivwits site.



Photograph C-10. Santa Clara River flooding near the Shivwits portion of the project area.



Photograph C-11. Santa Clara River flooding north of the Shivwits portion of the project area.



Photograph C-12. Site of proposed new basin site in Dammeron Valley.



Photograph C-13. Site of proposed new basin site in Dammeron Valley.



Photograph C-14. Existing Basin in Diamond Valley that would be repaired.



Photograph C-15. Existing Basin in Diamond Valley that would be repaired.



Photograph C-16. Existing Basin in Diamond Valley that would be repaired.



Photograph C-17. Damaged drainage channel in Diamond Valley.



Photograph C-18. Floodplain/ historic agriculture site near Santa Clara River.



Photograph C-19. Proposed pipeline would be attached to this bridge over Santa Clara River.



Photograph C-20. Shivwits area floodplain/historic agriculture field. Photograph taken from west side buffer area. Santa Clara River riparian area is to the east.



Photograph C-21. Buffer area on west side of Shivwits site. Santa Clara River riparian area is to the east.