


- Turn on GPS receiver, TSC2, and Blackberry.



Press Measure



Press VRS



If this message remains on the screen for longer than 30 seconds, the controller is not connecting with the receiver.

Press Cancel then proceed through the Bluetooth Settings Setup section found below.



If this message is displayed, the controller is not connecting to the internet. This indicates a problem with the Blackberry settings or the Access Internet setup.


First check the Blackberry settings by proceeding through the Checking Bluetooth Settings section of the Blackberry Setup Tab located in the Area 5 GPS manual.

If the error message still persists proceed through the Internet Setup section below.


Bluetooth Settings Setup




Press Instrument



Press GNSS Functions




Press Bluetooth




Ensure the Connect to GNSS rover box is set to the correct R8.

Example: If you are using TSC2 #3, the correct R8 would be R8-3.

Click Config



Ensure the Turn on Bluetooth box is checked. Then Click OK.




Click Accept. The Bluetooth setup is now complete.

Internet Setup



Click Internet Setup



Ensure the GPRS Connection: is set to the appropriate Blackberry.

Ensure the Bluetooth box is checked

Click Connect. The connection process may take a few seconds. If the connection is successful the box at the bottom should read: Internet Connection (Blackberry 4) established.