UNITED STATES
DEPARTMENT OF AGRICULTURE
NATURAL RESOURCES CONSERVATION SERVICE

LAKE COUNTY, OREGON, NORTHERN PART
CRACK IN THE GROUND QUADRANGLE
SHEET NUMBER 31 OF 89




This soil survey was compiled by the U.S. Department of Agriculture, Natural Resources Conservation Service and cooperating agencies. Base maps are orthophotographs prepared for the National Agriculture Imagery Program (NAIP), from 2005 aerial photography. Administrative boundaries were acquired from the State of Oregon. Boundaries may have been edited to conform with features represented on the publication orthophotography or to enhance the clarity of the soils information.

North American Datum of 1983(NAD83). GRS80 Spheroid 1000-meter ticks: Universal Transverse Mercator, zone 10. Coordinate grid ticks and land division data, if shown, are approximately positioned. Digital data are available for this quadrangle.

NORTH

QUADRANGLE LOCATION

SCALE 1:24000

MILES

FEET

KILOMETERS

| | | |
|---|---|---|
| 19 | 20 | 21 |
| 30 | | 32 |
| 41 | 42 | 43 |

19 HOGBACK BUTTE
20 JACKS PLACE
21 PETERS CREEK SINK
30 LANE LAKE
32 CHRISTMAS LAKE
41 THORN LAKE
42 CHRISTMAS VALLEY
43 FANDANGO CANYON

INDEX TO ADJOINING 7.5 MAPS

# CRACK IN THE GROUND, OREGON

7.5 MINUTE SERIES
SHEET NUMBER 31 OF 89

Soil map delineations extending beyond the dashed white quadrangle neatline are for reference only and are included on adjacent map sheets.